

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 3 – Wellhead Sign



Photo 4 – Heater Treater, Stained Soil STILL REMAINS for previous Inspection

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 5 – Stained Soil Eastside of the Gas Engine House




Photo 6 – Stained Soil inside the Gas Engine House

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041




Photo 7 – Stained Soil at Wellhead



Photo 8 – Debris in Containment. Wildlife Netting is missing

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 9 – ECD and Flare




Photo 10 – Standing Oil at ECD

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 11 –Standing Oil at Flare



Photo 12 – Standing Oil at Flare

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041




Photo 13 – Loadline Bucket at South Crude Oil Tank – Oily Waste and Lid Missing



Photo 14 – Loadline Bucket at South Crude Oil Tank – Oily Waste and Lid Missing. Stained Soil

Inspection Photos
Location Name: Buchner 1-2H
Location ID: 427041



Photo 15 – Loadline Bucket at Produced Water Tank – Oily Waste and Lid Missing



Photo 16 – Loadline Bucket at Produced Water Tank – Oily Waste and Lid Missing. Stained Soil