

## Grizzly Operating Mclaughlin Location # 335082



location



location



# Grizzly Operating Mclaughlin Location # 335082

Feb 5, 2021 at 11:49:35 AM  
39.501359,-107.647473 ±79.88m  
COGCC



location

Feb 5, 2021 at 11:50:15 AM  
39.500997,-107.647605 ±4.78m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Grizzly Operating McLaughlin Location # 335082



**Previous inspection photo of lack of stabilization**



**Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Grizzly Operating McLaughlin Location # 335082



**Previous inspection photo of lack of stabilization**



**Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Grizzly Operating McLaughlin Location # 335082



**Previous inspection photo of lack of stabilization**



**Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources