

Grizzly Operating Stranahan 41C Location # 335437

Feb 5, 2021 at 11:57:09 AM
39.503648,-107.649778 ±4.34m
OGCC



location

Feb 5, 2021 at 11:57:46 AM
39.503579,-107.649890 ±4.83m
OGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 41C Location # 335437



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Stranahan 41C
Location # 335437**



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



**Grizzly Operating
Stranahan 41C
Location # 335437**



Previous inspection photo of lack of stabilization



**Follow up inspection photo shows that nothing has
been done about the lack of stabilization on the pad**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 41C Location # 335437



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 41C Location # 335437



Previous inspection photo of lack of stabilization



Follow up inspection photo shows that nothing has been done about the lack of stabilization on the pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Stranahan 41C Location # 335437



Lack of stabilization



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources