

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402593483

Date Received:

02/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10646

Name of Operator: AXIS EXPLORATION LLC

Address: 370 17TH ST SUITE 5200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Extraction

720-370-5540

COGCCInspections@extractionog.com

Antonioli, Philip

720-345-4603

PAntonioli@extractionog.com

Nathan Bennett

720-354-4616

nbennett@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688309589

Inspection Date: 01/28/2021

FIR Submit Date: 02/01/2021

FIR Status: _____

Inspected Operator Information:

Company Name: AXIS EXPLORATION LLC

Company Number: 10646

Address: 370 17TH ST SUITE 5200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 322205

Location Name: SABO 22-19-66S62W Number: 19SENW County: ELBERT

Qtrqtr: SENW Sec: 19 Twp: 6S Range: 62W Meridian: 6

Latitude: 39.515100 Longitude: -104.378470

FACILITY - API Number: 05-039- -00 Facility ID: 209691

Facility Name: SABO 22-19 Number: 4

Qtrqtr: SENW Sec: 19 Twp: 6S Range: 62W Meridian: 6

Latitude: 39.515100 Longitude: -104.378470

CORRECTIVE ACTIONS:

1 ☒ CA# 146204

Corrective Action: Engine leaking on ground (see attached photo).
Corrective Action: Non E&P Waste not properly stored, handled, transported, treated,
or disposed per Rule
907A. Requires appropriate cleanup.
Date: 04/24/2020

Date: _____

Response: CA COMPLETED

Date of Completion: 02/05/2021

Operator Comment: - All equipment washed to remove grime, grease, and oil buildup.
- Stained soil excavated and disposal of according to AXIS waste disposal manifest.
- Two tandem-truck loads of road base used to replace excavated materials and dress up surrounding area.
- Empty drum and containment removed from location and taken to XOG yard.
- Sludge removed from location; equipment secured.

COGCC Decision: Approved via an AMI

COGCC Representative: Will reinspect.

2 ☒ CA# 146205

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Requires appropriate cleanup.

Date: 04/24/2020

Response: CA COMPLETED

Date of Completion: 02/05/2021

Operator Comment: - All equipment washed to remove grime, grease, and oil buildup.
- Stained soil excavated and disposal of according to AXIS waste disposal manifest.
- Two tandem-truck loads of road base used to replace excavated materials and dress up surrounding area.
- Empty drum and containment removed from location and taken to XOG yard.
- Sludge removed from location; equipment secured.

COGCC Decision: Approved via an AMI

COGCC Representative: Will reinspect

OPERATOR COMMENT AND SUBMITTAL

Comment: Findings of inspection report have been addressed and rectified. Work was completed on Friday, 02/05/2021.

Photo Log has been included as an ATTACHMENT. All pictures were taken following the conclusion of the necessary work. Date of photos is 02/05/2021.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nathan Bennett

Signed: _____

Title: Regulatory Supervisor

Date: 2/8/2021 8:28:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402593483	FIR RESOLUTION SUBMITTED
402593496	Photo Log of Location & Equipment

Total Attach: 2 Files