

Inspection Photos
Location Name: FURROW USX /AB15-04P
Location #: 416705




Photo #1

Furrow USX AB15-04P (05-123-31460)

Abandoned Location | AL

~ 40 yds.

No disturbance or evidence of oil & gas activity