

Inspection Photos

Loc#334890

Operator: Caerus

Insp#: 692402998

Insp Date: 2/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

February 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Dever Loc#334890



Photo#2:
Area behind tanks.



Photo#3:
Area on West pad perimeter.

Feburary 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Dever Loc#334890