

# *Inspection Photos*

*Loc#334906*

*Operator: Caerus*

*Insp#: 692403002*

*Insp Date: 2/5/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South.

Feburary 5, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Benzel Loc#334906



Photo#2:  
Rutting in Pad traffic pattern.

Feburary 5, 2021



Photo#3:  
Area on West pad perimeter.

Caerus Benzel Loc#334906