

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402596461

Date Received:
02/10/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Ried, Jordan</u>	<u>970-563-4000</u>	<u>maralextechjr@gmail.com</u>
<u>-</u>		<u>dnr_cogccengineering@state.co.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>Browning, Chuck</u>	<u>970-433-4139</u>	<u>chuck.browning@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693801227
Inspection Date: 11/05/2019 FIR Submit Date: 11/06/2019 FIR Status: _____

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 312479

Location Name: PAVLAKIS-69S100W Number: 5NWSE County: MESA
Qtrqtr: NWSE Sec: 5 Twp: 9S Range: 100W Meridian: 6
Latitude: 39.301717 Longitude: -108.573569

FACILITY - API Number: 05-077-00 Facility ID: 221732

Facility Name: PAVLAKIS Number: 1-5 RR
Qtrqtr: NWSE Sec: 5 Twp: 9S Range: 100W Meridian: 6
Latitude: 39.301717 Longitude: -108.573569

CORRECTIVE ACTIONS:

1 CA# 133278

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 11/22/2019

Response: CA COMPLETED

Date of Completion: 12/28/2020

Operator Comment: Markers installed

COGCC Decision: _____

COGCC Representative: _____

2 CA# 133279

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. CA from previous inspection not completed. CA date remains the same as previous inspection.

Date: _____

Response: CA COMPLETED Date of Completion: 12/28/2020

Operator Comment: Successful MIT completed December 28, 2020. Form 21 - Mechanical Integrity Test, Doc. No. 402561071, attached.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: SUCCESSFUL MIT PERFORMED 12/28/2020. FORM 21 ATTACHED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Diane Togstad Signed: _____

Title: Land Technician/Reg. Comp Date: 2/10/2021 10:53:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402596467	FORM 21 MECHANICAL INTEGRITY TEST

Total Attach: 1 Files