



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bird Protectors # 3

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.206510,-104.796490

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Paint**

Condition

Other (Content)

Other (Capacity) 150 Bbl	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		40.206610,-104.796610

Comment:	
Corrective Action:	Date:

**Paint**

Condition		
-----------	--	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		40.206510,-104.796490

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.206610,-104.796610

Comment:	
Corrective Action:	Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	150 Bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number
123-19948
123-19764
123-20308
123-14115

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 246318 Type: WELL API Number: 123-14115 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine wellhead and battery inspection.</a>	carlilec	02/10/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690007092	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5349060">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5349060</a>