

Inspection Photos

API: 043-40017

Operator: JAVERNICK OIL

Inspection Date: 2/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40017 | Date: 2/9/2021

Inspection Photos



Photo 1. Facing east toward the location. Well sign has been updated.



Inspection Photos



Photo 2. Facing northeast toward the location. Unused equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40017 | Date: 2/9/2021

Inspection Photos



Photo 3. Unused areas around the well need to be reclaimed. There is a lack of vegetation interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40017 | Date: 2/9/2021