

# Inspection Photos

API: 043-40016

Operator: JAVERNICK OIL

Inspection Date: 2/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the location. Well sign has been updated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40016 | Date: 2/9/2021

## Inspection Photos



**Photo 2.** Facing south toward the location. Unused equipment has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40016 | Date: 2/9/2021

## Inspection Photos



**Photo 3.** Unused areas around the well need to be reclaimed. The vegetation has not established in the interim reclamation area surrounding the equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40016 | Date: 2/9/2021