

Inspection Photos

2/8/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 323867

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323867



Photo 1: Photo taken from the west end of the Location, facing northeast. Photos 1-2 provide an overview of the Location from northeast to east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323867



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323867



Photo 3: Photo taken from the south end of the Location, facing southeast. Photo shows pad perimeter and southern interim areas. Limited visibility due to snow cover preventer and accurate assessment of the reclamation.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323867



Photo 4: Photo of well.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323867



Photo 5: Photo of 400 bbl condensate tank w/ emergency contact numbers.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323867



Photo 6: Photo taken from the northeast corner of the Location, facing south. Photo 6-7 provide an overview of the Location from south to west



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323867



Photo 7: See comments under photo 6.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources