




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill Unit 19-44

API: 05-103-10216

Inspection: 700405292



40.12172, -108.20028, 6032.8ft, 51°
02/02/2021 02:38:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Ant Hill Unit 19-44

API: 05-103-10216

Inspection: 700405292



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well.

Ant Hill Unit 19-44

API: 05-103-10216

Inspection: 700405292







COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tanks.

Ant Hill Unit 19-44

API: 05-103-10216

Inspection: 700405292



40.12176, -108.20018, 6027.5ft, 341°
02/02/2021 02:38:34 PM