



40.11809, -108.18699, 6004.8ft, 55°  
02/02/2021 02:59:09 PM




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Ant Hill Unit 29-13**

**API: 05-103-10210**

**Inspection: 700405294**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources


**Photo 2. Well.**

**Ant Hill Unit 29-13**

**API: 05-103-10210**

**Inspection: 700405294**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Casing gage.**

**Ant Hill Unit 29-13**

**API: 05-103-10210**

**Inspection: 700405294**



40 11805, -108 18664, 5996.6ft, 44°  
02/02/2021 02:56:20 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Meter building & separator.**

**Ant Hill Unit 29-13**

**API: 05-103-10210**

**Inspection: 700405294**





40.11814, -108.1866, 6000.4ft, 40°  
02/02/2021 02:56:50 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Separator.**

**Ant Hill Unit 29-13**

**API: 05-103-10210**

**Inspection: 700405294**



40.11819, -108.18694, 5995.1ft, 87°  
02/02/2021 02:58:28 PM