



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**WRD Unit Grady 20-44**

**API: 05-103-10133**

**Inspection: 700405296**



40.12185, -108.18207, 6010.0ft, 32°  
02/02/2021 03:10:10 PM





40.12205, -108.18172, 6024.4ft, 8°  
02/02/2021 03:10:56 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Well. Gas leak.**

**WRD Unit Grady 20-44**


**API: 05-103-10133**

**Inspection: 700405296**



40.12207, -108.1817, 6022.3ft, 12°  
02/02/2021 03:17:48 PM





40.12211, -108.18169, 6024.4ft, 6°  
02/02/2021 03:11:14 PM



40.12178, -108.18158, 6017.4ft, 1°

02/02/2021 03:20:50 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Tanks.**

**WRD Unit Grady 20-44**

**API: 05-103-10133**

**Inspection: 700405296**





