



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

WRD Unit 28-11

API: 05-103-10116

Inspection: 700405299



40.11953, -108.17733, 5980.6ft, 39°
02/02/2021 03:32:48 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Photo 2. Well.

WRD Unit 28-11

API: 05-103-10116

Inspection: 700405299

40.11958, -108.17727, 5980.4ft, 288°
02/02/2021 03:37:27 PM





40.11959, -108.17719, 5994.7ft, 89°
02/02/2021 03:33:36 PM



40.11982, -108.17735, 5993.0ft, 66°
02/02/2021 03:35:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

WRD Unit 28-11

API: 05-103-10116

Inspection: 700405299



40.11955, -108.1773, 5982.4ft, 163°
02/02/2021 03:32:59 PM