

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /14-1 Pad

Location ID: 334496



Photo #2888 from entrance to location.



Photo #2889 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC McDaniel /14-1 Pad

Location ID: 334496



Photo #2890 Dump line heating insulation open ended and not capped.