

Inspection Photos
Location Name: Dutch Lake 09-11H
Location ID: 422932



Photo 1 – Wellhead

Photo 2 – Pumping Unit

Inspection Photos
Location Name: Dutch Lake 09-11H
Location ID: 422932



Photo 3 – Tank Battery

Photo 4 – Tank Battery Sign


Inspection Photos
Location Name: Dutch Lake 09-11H
Location ID: 422932




Photo 5 – Flare and ECD

Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Dutch Lake 09-11H
Location ID: 422932



Colorado Oil and Gas Conservation Commission
40.49565, -104.29249, 4686.2ft, 267°
02/02/2021, 14:09:44



Colorado Oil and Gas Conservation Commission
40.49565, -104.29249, 4675.3ft, 331°
02/02/2021, 14:09:48

Photo 7 – Unmarked Risers

Photo 8 – Unmarked Risers

Inspection Photos
Location Name: Dutch Lake 09-11H
Location ID: 422932



Photo 9 – Unmarked Risers

Photo 10 – Unused Parts in Berm