



40.09456, -108.2147, 5737.1ft, 175°  
02/03/2021 12:30:19 PM



40.09436, -108.21469, 5733.8ft, 64°  
02/03/2021 12:31:02 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 2. Fee M-31-2-96N (05-103-09467).

Fee M-31-2-96N, Ant Hill 6-11 D  
API: 05-103-09467, 10406 Inspection: 700405309



40.09454, -108.21467, 5716.7ft, 294°  
02/03/2021 12:38:28 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 3. Ant Hill Unit 6-11 D (05-103-10406).

Fee M-31-2-96N, Ant Hill 6-11 D  
API: 05-103-09467, 10406 Inspection: 700405309




40.09416, -108.21464, 5720.8ft, 69°  
02/03/2021 12:31:36 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Meter buildings.**

**Fee M-31-2-96N, Ant Hill 6-11 D**  
**API: 05-103-09467, 10406 Inspection: 700405309**



40.0942, -108.21467, 5723.3ft, 320°  
02/03/2021 12:33:05 PM

