



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**CRU 4401D-A23-1N100      API: 05-103-10561**  
**Inspection: 700405313**





40.0463, -108.57548, 6869.8ft, 110°  
02/03/2021 01:46:21 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack.**

**CRU 4401D-A23-1N100**

**API: 05-103-10561**

**Inspection: 700405313**



40.04626, -108.57545, 6874.4ft, 44°  
02/03/2021 01:46:34 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Well.**

**CRU 4401D-A23-1N100**

**API: 05-103-10561**

**Inspection: 700405313**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Meter / separator building.**

**CRU 4401D-A23-1N100      API: 05-103-10561**  
**Inspection: 700405313**



40.04647, -108.57508, 6870.4ft, 357°  
02/03/2021 01:47:21 PM





40.04613, -108.57598, 6870.5ft, 145°  
02/03/2021 01:51:30 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Tank.**

**CRU 4401D-A23-1N100**

**API: 05-103-10561**

**Inspection: 700405313**

