

# Grizzly Operating Circle B3 Location # 334629

Feb 9, 2021 at 12:49:15 PM  
39.482821,-107.640065 ±5.01m  
COGCC



location

Feb 9, 2021 at 12:54:09 PM  
39.483002,-107.640488 ±4.75m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Grizzly Operating  
Circle B3  
Location # 334629



location



**Grizzly Operating  
Circle B3  
Location # 334629**

Feb 9, 2021 at 12:51:17 PM  
39.482724,-107.640127 ±4.76m  
COGCC



**Lack of stabilization**

Feb 9, 2021 at 12:54:20 PM  
39.483039,-107.640597 ±4.77m  
COGCC



**Lack of stabilization**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Grizzly Operating  
Circle B3  
Location # 334629**



**Lack of stabilization from previous inspection**



**Lack of stabilization from follow up inspection**