

Inspection Photos

Loc#335544

Operator: Ursa

Insp#: 692403014

Insp Date: 2/10/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Norcross Loc#335544



Photo#2:
Unmarked Anchor; long view.



Photo#3:
Unmarked Anchor; close up.

February 10, 2021

Ursa Norcross Loc#335544



Photo#4:
Unstable slope behind separators.



Photo#5:
Unstable slope behind separators.

February 10, 2021

Ursa Norcross Loc#335544



Photo#6:
Interim area.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa Norcross Loc#335544