

Inspection Photos

Loc#335273

Operator: Terra

Inspection Number: 692403017

Inspection Date: 2/10/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Interim Reclamation area .

February 10, 2021



Photo#2:
Rutting, degradation of pad surface.

Photo#3:
Rutting, degradation of pad surface.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335273