

# *Inspection Photos*

*Loc#335251*

*Operator: Terra*

*Inspection Number: 692403016*

*Inspection Date: 2/10/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location to Northwest.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335251





Photo#2:  
Rutting, degradation of pad surface.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Rutting, degradation of pad surface.

Inspection Photos: Terra Clough Loc#335251