

Inspection Photos

API: 071-08063

Operator: OGRIS OPERATING LLC

Inspection Date: 2/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08063 | Date: 2/12/2021

Inspection Photos



Photo 1. Facing north along the main road. Erosion along the road side has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 2/12/2021

Inspection Photos



Photo 2. The culvert along the road has been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 2/12/2021

Inspection Photos



Photo 3. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08063 | Date: 2/12/2021