

Inspection Photos
Operator: Simcoe
API: 067-06662
Date: 2/8/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, and sand dropseed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with understory of sagebrush, snakeweed, and James galleta.