

# Inspection Photos

API: 071-06858

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 1.** Facing west along the main road. Erosion along the road has been repaired and BMP's have been installed and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 2.** Outlet protection has been installed at Lat/Long:37.15900,-104.81291.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 3.** Facing west along the main road. The side of the road has been repaired with BMP's installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 4.** Facing southwest along the main road. Gravel has been installed along this area of the road. Rock rip/rap has been installed for erosion control.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 5.** Facing north along the main road near the location. The side of the road has been repaired with BMP's installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 6.** The side of the access road has been seeded and hydromulched.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021

## Inspection Photos



**Photo 7.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 2/12/2021