

Inspection Photos
Operator: Simcoe
API: 067-06994
Date: 2/11/2021



COLORADO
Department of
Natural Resources



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with crested wheatgrass, smooth brome, and western wheatgrass.



Photos 3. View of the southern project area from the southwestern corner facing eastward.



Photos 4. View of dense musk thistles observed along the access road. Approximately 1000 individuals observed along the access road and within the project area.



Photo 5 View of the reference area comprised of irrigated grass field in dormant vegetative condition.