

Inspection Photos

Loc#335284

Operator: Terra

Inspection Number: 692403019

Inspection Date: 2/10/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

This is a two level site with Wells located on a teardrop pad to South of equipment.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335236



Photo#2:
Rutting, sloppy conditions at Well head area.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Rutting, sloppy conditions leading into Well
head area.

Inspection Photos: Terra Clough Loc#335236



Photo#4:
Interim area.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Developing subsidence/ tunneling.

Inspection Photos: Terra Clough Loc#335236