

# *Inspection Photos*

*Loc#322440*

*Operator: Terra*

*Inspection Number: 692403020*

*Inspection Date: 2/10/21*





Photo#1:  
Overview of Location to Northeast.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#322440



Photo#2:  
Overview of Location to North; Compressor Station in background.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Loc#322440