

# *Inspection Photos*

*Loc#323788*

*Operator: Mustang*

*Insp#: 692403023*

*Insp Date: 2/10/21*





Photo#1:

View of Location to South; note heavy weed infestation.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Mustang Resources Moore Loc#323788



Photo#2:  
View of Location to North; note degradation of site.

February 10, 2021



Photo#3:  
Close up of rutting.



Photo#4:  
Close up of rutting.

February 10, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Mustang Resources Moore Loc#323788