


Issue Report

Tres Hombres 1-22, 061-06894

Report created on February 9, 2021

Captured: February 1, 2021



Type	Count
Erosion	4
Stressed Vegetation	1

No.	Summary	Type	Created	Status
5	South side of location outside of fencing with drifting dirt (Blow out).	Erosion	Feb 9, 2021 at 3:21pm	Open
4	Drifting dirt around minimal vegetation.	Erosion	Feb 9, 2021 at 3:19pm	Open
3	Back ground area vegetation with some wind erosion.	Stressed Vegetation	Feb 9, 2021 at 3:16pm	Open
2	Drifting dirt around minimal vegetation.	Erosion	Feb 9, 2021 at 3:14pm	Open
1	Minimal vegetation with dirt drifting around vegetation	Erosion	Feb 9, 2021 at 3:12pm	Open

Erosion

No. 1 OPEN

Captured: Feb 1, 2021 at 11:45am



Type

Erosion

Lat/Long

38.47944, -102.67218

Summary

Minimal vegetation with dirt drifting around vegetation

Created

Feb 9, 2021 at 3:12pm by Craig Quint

No. 2 OPEN**Captured:** Feb 1, 2021 at 11:45am**Type**

Erosion

Lat/Long

38.47874, -102.67227

Summary

Drifting dirt around minimal vegetation.

Created

Feb 9, 2021 at 3:14pm by Craig Quint

No. 4 OPEN

Captured: Feb 1, 2021 at 11:45am

**Type**

Erosion

Lat/Long

38.47912, -102.67175

Summary

Drifting dirt around minimal vegetation.

Created

Feb 9, 2021 at 3:19pm by Craig Quint

No. 5 OPEN

Captured: Feb 1, 2021 at 11:45am

**Type**

Erosion

Lat/Long

38.47864, -102.67170

Summary

South side of location outside of fencing with drifting dirt (Blow out).

Created

Feb 9, 2021 at 3:21pm by Craig Quint

Stressed Vegetation

No. 3 OPEN

Captured: Feb 1, 2021 at 11:45am



Type

Stressed Vegetation

Lat/Long

38.47989, -102.67179

Summary

Back ground area vegetation with some wind erosion.

Created

Feb 9, 2021 at 3:16pm by Craig Quint

