

Grizzly Operating Kaufman 2 Location # 426397

Feb 17, 2021 at 10:20:50 AM
COGCC



location

Feb 17, 2021 at 10:20:53 AM
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Kaufman 2 Location # 426397

Feb 17, 2021 at 10:28:24 AM
39.502543,-107.618409 ±4.73m
COGCC



Location/ battery signage at separators before
pumper moved

Feb 17, 2021 at 10:29:01 AM
39.501804,-107.618950 ±4.76m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Kaufman 2 Location # 426397



Pumper moved Battery signage to tank battery from separators while I was on location



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Kaufman 2 Location # 426397

Feb 17, 2021 at 10:24:37 AM
39.502193,-107.618549 ±4.76m
COGCC



Lack of stabilization

Feb 17, 2021 at 10:24:32 AM
39.502193,-107.618549 ±4.76m
COGCC



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Kaufman 2 Location # 426397

Feb 17, 2021 at 10:28:07 AM
39.502543,-107.618409 ±4.73m
COGCC



Lack of stabilization

Feb 17, 2021 at 10:32:26 AM
39.501572,-107.618902 ±4.79m
COGCC



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources