

Grizzly Operating Kaufman 6 Location # 418772

Feb 17, 2021 at 1:48:24 PM
39.515806,-107.614829 ±4.86m
COGCC



location

Feb 17, 2021 at 1:51:33 PM
39.516019,-107.614575 ±4.79m
COGCC



location

Grizzly Operating Kaufman 6 Location # 418772

Feb 17, 2021 at 1:53:32 PM
39.516005,-107.614950 ±4.76m
COGCC



**Location/battery signage in front of separators
before pumper move to correct location**

Feb 17, 2021 at 1:57:11 PM
39.515974,-107.615065 ±4.72m
COGCC



location/battery signage now at tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Kaufman 6 Location # 418772



Lack of stabilization/entrance looking south



**Lack of stabilization/entrance looking north into
location**



Grizzly Operating Kaufman 6 Location # 418772



Lack of stabilization



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Kaufman 6
Location # 418772**



Lack of stabilization



Lack of stabilization



Grizzly Operating Kaufman 6 Location # 418772



Lack of stabilization



Lack of stabilization



**Grizzly Operating
Kaufman 6
Location # 418772**



Previous inspection of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources