

Inspection Photos

API: 071-06582

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/17/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06582 | Date: 2/17/2021

Inspection Photos



Photo 1. Facing south along the access road. Additional gravel has been applied to the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06582 | Date: 2/17/2021

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-06582 | Date: 2/17/2021

Inspection Photos



Photo 3. Facing toward the pit. Water level was about 6inches from the freeboard marker.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06582 | Date: 2/17/2021

Inspection Photos



Photo 4. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06582 | Date: 2/17/2021