

# Inspection Photos

2/17/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334744

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334744



**Photo 1:** Photo taken from the southeastern corner of the Location, facing west. Photo provide and overview of the Location.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 2:** Photo taken from the southeastern corner of the Location, facing north. Photo provide and overview of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 3:** Photo shows example of marked anchors observed on the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 4:** Photo shows sediment trap observed on the east end of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 5:** 200 bbl produced water tank and containment bmp.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 6:** Photo taken from the west end of the Location, facing south. Photo shows visible vegetative establishment is perennial vegetation.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 7:** Photo shows sediment trap on the southeast corner of the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334744



**Photo 8:** Photo taken from the east end of the Location, facing west. Photo shows the 4 producing wells on the Location.