

Inspection Photos

2/17/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334730

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334730



Photo 1: Photo taken from the northeast end of the Location, facing southwest. Photos 1-2 provide an overview of the Location from southwest to northwest.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334730



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334730



Photo 3: Photo shows unused fence panels stored behind the separators.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334730



Photo 4: Photo shows unused fence panels stored on the ground behind the tanks on the south end of the location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334730



Photo 5: Photo taken from the interim areas on the northwest end of the Location, facing north. Photo shows interim areas appeared to have been ripped once, in one direction rather than cross-ripped pursuant to Rule 1003.c. Due to frozen conditions, Reclamation Specialist was unable to dig a test pit; a followup inspection will be conducted in the future growing season to determine compliance with 1003 Rules and requirements.

