

# Interim Reclamation Inspection

February 16, 2021

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 320644

Inspection Document #: 697502571

Arapahoe County, CO

SWSW Section 25 T5S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 1.** Photo taken of the Operator sign at the tank battery.





Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 2.** Photo taken from the western tank battery, facing South. Photo illustrates unmanaged weeds.





Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 3.** Photo taken from the eastern tank battery, facing East. Photo illustrates stormwater erosion due to concentrated runoff from the tank battery location.



Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 4.** Photo taken from the eastern tank battery, facing West. Photo illustrates stormwater erosion due to concentrated runoff from the tank battery location.



Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 5.** Photo taken from the southern tank battery, facing East. Photo illustrates risers from a previous meter house.



Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 6.** Photo taken from the well location, facing South. Photo illustrates unmanaged weeds.





Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 7.** Photo taken from the western well location, facing East. See comments under Photo 6.





Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644




**Photo 8.** Photo taken from the well location, facing West. See comments under Photo 6.





Inspection Photos  
Location Name: Lowry State #13-25  
Location ID: 320644



**Photo 9.** Google Earth aerial imagery taken 6/9/2017 illustrating the stormwater erosion from the tank battery.