

# *Inspection Photos*

*Loc#324259*

*Operator: Terra*

*Inspection Number: 692403043*

*Inspection Date: 2/11/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry.

February 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough Tank Loc#324259



Photo#2:  
Soft, sloppy conditions at Well head area.



Photo#3:  
Sediment migrating @ Northwest corner.

February 11, 2021



Photo#4:  
Erosion occurring on North cut behind tanks.

February 11, 2021



Photo#5:  
Erosion occurring at power pole.




Photo#6:  
East perimeter berm and wattles.

February 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#7:  
Area of berm hydro-mulched.

Inspection Photos: Terra Clough Tank Loc#324259