



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Pump jack.**

**M.V. Smith 31**

**API: 05-103-05344**

**Inspection: 700405463**





40.07565, -108.84629, 5162.0ft, 61°  
02/18/2021 03:35:10 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**M.V. Smith 31**

**API: 05-103-05344**

**Inspection: 700405463**



40.07567, -108.84629, 5154.1ft, 38°  
02/18/2021 03:43:59 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Well gas venting.**

**M.V. Smith 31**

**API: 05-103-05344**

**Inspection: 700405463**





40.07566, -108.84628, 5153.0ft, 4°  
02/18/2021 03:43:22 PM









40.07621, -108.84457, 5158.9ft, 18°  
02/18/2021 03:30:46 PM