

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> ROBERT BURCH	<b>Facility ID:</b> 117868
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> AMOCO PRODUCTION COMPANY / 2500	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b> 697802	<b>Permit Date:</b> 6/9/1977
<b>Related Facilities:</b> ROBERT M BURCH GAS UNIT #1 (API 123-08345; Facility ID 240557; Loc ID 318074)	

<b>County:</b> WELD			
<b>Township:</b> 3N	<b>Range:</b> 68W	<b>Section:</b> 14	<b>QQ:</b> SWSW
<b>Original Latitude/ Longitude:</b> 40.220775 / -104.977377			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |   |                 |
|---|-----------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 697802          | Date: 6/9/1977  |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 643322         | Date: 1/22/1996 |
| Doc #: 200027112  | Date: 6/5/2002  |
| Doc #:  | Date:           |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #:              | Date:           |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #:                          | Date:           |
| <input type="checkbox"/> COGIS Document – Doc #:                                | Date:           |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986              | Date: 1/21/1997 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #:                 |                 |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) |                 |
| <input type="checkbox"/> Other:   |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

No evidence of a pit on location

#### Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were replaced by a fiberglass tank prior to 1/22/1996 field inspection. Field inspections and 1997 pit inventory report document a 75bbl fiberglass tank on location. Associated well PA 5/20/2016. Pit Status has been changed to closed.

