

Pit Status Evaluation Form

Pit Overview:

Pit Name: DOMENCIO 1	Facility ID: 118833
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: BARRETT RESOURCES CORP / 6495	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: DOMENICO #1 (API 123-10453; Facility ID 242662; Loc ID 318994)	

County: WELD			
Township: 2N	Range: 68W	Section: 9	QQ: SWNE
Original Latitude/ Longitude:		/	
Updated Latitude/ Longitude:		/	
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 500165632 | Date: 4/29/1998 |
| | Doc #: 200072521 | Date: 6/13/2005 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223763 | Date: 1/29/1998 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 3/23/2020

Timing of Pit Closure:

Closed prior to 1998 pit inventory report

Pit Status Review Summary:

Based on records review and aerial imagery any pits on location were replaced by a tank prior to 1998 pit inventory report. Pit inventory and inspections document a concrete vault on location. Associated well PA 9/30/2013. Pit Status has been changed to closed.

