

Inspection Photos
Location Name: Wildhorse 06-0634H
Location ID: 427410



Photo 1 – Tank Battery



Photo 2 – Tank Battery

Inspection Photos
Location Name: Wildhorse 06-0634H
Location ID: 427410



Photo 3 – Tank Battery Sign. H2O Tank Signage missing

Photo 4 – Exhaust

Inspection Photos
Location Name: Wildhorse 06-0634H
Location ID: 427410



Photo 5 – Wellhead



Photo 6 – Stained Soil at Wellhead



Inspection Photos
Location Name: Wildhorse 06-0634H
Location ID: 427410



Photo 7 – Wellhead