



Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On February 18, 2021, produced water released from the main water trunk line at the Newby 15-33HZ facility. Assessment activities are ongoing. The assessment details will be summarized in a supplemental report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
2/18/2021	Weld County	Weld County	-	Notified via Email
2/18/2021	City of Longmont	Landowner	-	Notified via Email

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

Was there damage during excavation? Yes ☐ No ☒

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

**OPERATOR COMMENTS:**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Greg Hamilton

Title: Environmental Consultant Date: 02/19/2021 Email: Gregory\_Hamilton@oxy.com

**COA Type**

**Description**

--	--

**Attachment List**

<u>Att Doc Num</u>	<u>Name</u>
402603931	OTHER
402604114	TOPOGRAPHIC MAP

Total Attach: 2 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)