


**Inspection Photos**  
**Location Name: Greasewood 08-18H**  
**Location ID: 423895**



**Photo 1 – Pumping Unit**



**Photo 2 – ECD**

**Inspection Photos**  
**Location Name: Greasewood 08-18H**  
**Location ID: 423895**



**Photo 3 – Tank Battery**

**Photo 4 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: Greasewood 08-18H**  
**Location ID: 423895**



**Photo 5 – Wildlife Netting has been installed**



**Photo 6 – Separators**



**Inspection Photos**  
**Location Name: Greasewood 08-18H**  
**Location ID: 423895**



**Photo 7 – Riser has been marked**



**Photo 8 – Risers have been marked**

