

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2021

Submitted Date:

02/20/2021

Document Number:

688309724

**FIELD INSPECTION FORM**

Loc ID 431489 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96340  
Name of Operator: WIEPKING-FULLERTON ENERGY LLC  
Address: 106 GLENMOOR LN  
City: ENGLEWOOD State: CO Zip: 80113

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	<a href="#">All Inspections</a>
Halde, Kerry	(719) 340-0329	haldeoil@hotmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431492	WELL	AL	05/15/2018	LO	073-06504	Raptor 3	AL

**General Comment:**

AL Inspection, Form 4 #401640533 requested 5/18/2021. "The Raptor 3 well has not been spud and is not drilling. The operator filed previous sundrys, which were approved, allowing the operator to build a drilling pit at the site of the Raptor 3. The pit was used for drilling mud from the Raptor 4 location and the Good Deal 13 location with the permission of the COGCC. Since the pit site is undergoing reclamation, the operator is not able to file a Form 4 sundry to cancel the location permit." Form 2 and 2A have expired; 1/30/215 1/20/2106 respectively.

Location was never drilled however from previous inspections a drill pit was made and used to two nearby wells. The pit was closed and the site reclaimed and is fenced in pasture. Reclamation status looks to be in process and should pass final reclamation. Therefore the entire site should be in Final Reclamation process so operator can contact COGCC permitting (CR) to determine proper closure process.

**Inspected Facilities**

Facility ID: 431492 Type: WELL API Number: 073-06504 Status: AL Insp. Status: AL

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688309750	Wiepking-Fullerton Raptor 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5356648">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5356648</a>