

Inspection Photos

Loc#335159

Operator: Terra

Inspection Number: 692403059

Inspection Date: 2/12/21





Photo#1:

View over Location entry to Southeast. Note rutting off edge of access road

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335159



Photo#2:
What appears to be new Interim installed.




Photo#3:
What appears to be new Interim installed.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335159



Photo#4:
Rutting and disruption of West side access road.




Photo#5:
Track/short-cut between tanks & separators.

February 12, 2021



Photo#6:
Rutting on equipment area track.

February 12, 2021



Photo#7:
Rutting on equipment area track.

Inspection Photos: Terra Clough Loc#335159



Photo#8:
Pad appears unstable and is rutted.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335159