

Inspection Photos

Loc#311542

Operator: Mustang

Inspection Number: 692403060

Inspection Date: 2/12/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Wellhead to Southwest.



Photo#2
Excavation at NW corner.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Clough Fed Loc#311542



Photo#3:
Rutting on portions of site.

February 12, 2021



Photo#4:
Anchor not marked with bright color.