

Inspection Photos

Loc#311542

Operator: Mustang

Insp#: 692403061

Insp Date: 2/12/21





Photo#1:
View over Wellhead to Southwest.



Photo#2
Excavation at NW corner.



February 12, 2021




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Clough Fed Loc#311543



Photo#3:
Rutting on portions of site.



Photo#4:
Anchor not marked with bright color.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Clough Fed Loc#311543