

Interim Reclamation Inspection

February 16, 2021

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 320706

Inspection Document #: 697502574

Arapahoe County, CO

SESW Section 15 T5S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 1. Photo taken from the well location, facing West. Photo illustrates all equipment has been removed from the well location and the nearby tank battery.



Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 2. Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: STATE B #1
Location ID: 320706



Photo 3. Photo taken from a portion of the lease road, facing Northwest. Photo illustrates the lease road has not been reclaimed.

